

QUESTION:

RFI #1 – Regarding the trench located on the “plan south” side of the new EDM machine, the Statement of Work Scope calls for “a new cast-in-place concrete trough in the floor.” However, Section A/S-102 shows a steel trench. Please review and clarify.

ANSWER:

Disregard the note on the drawing calling for a steel trench insert. The trench shall be as per the Statement of Work which calls for a cast in place concrete trench.

Please consider the above information when preparing you proposals.

Thank you,

Allen G. Derby
Subcontract Manager
5 Manhattan Square
Hampton, VA 23666
Office: (757)224-7865
Fax: (757)224-7888
Cell: (757)268-2003